



Note 1: Resistors in boxes are under the LM324 IC.
 Note 2: C15 was 2.2uF. Replaced with 4.7uF and C16 not populated to simplify design.

SEIBU HB-45A

Reverse-Engineered
By:

GURU
<https://gurudumps.blogspot.com>

Date: 03/01/2023 10:00PM

Sheet: 1/1

REV: A